

封装

封装名	外形尺寸图	推荐焊盘尺寸图
<p>QFP-100A</p>	<p>Top view dimensions: 80, 51, 14.0±0.2, 17.2±0.3, 20.0±0.2, 23.2±0.3, 81, 100, 30, 50, 31.</p> <p>Side view dimensions: 0.15^{+0.08}/_{-0.04}, 0.8±0.20, 0~10°.</p> <p>Detail view dimensions: 0.65, 0.30^{+0.10}/_{-0.08}, 0.10, 0.13, 0.35^{+0.15}/_{-0.10}, 3.22±0.18, (2.79).</p>	<p>Pad layout dimensions: 0.65, 1.5, 0.35, 14.6, 20.6.</p>
<p>SC-82ABA</p>	<p>Top view dimensions: 2.0±0.1, 1.3±0.2, 0.3, 0.3, 1.25±0.1, 0.3, 0.3, 1, 2, 0.4, (0.15).</p> <p>Side view dimensions: 0.125^{+0.100}/_{-0.025}, (0.3), 2.1±0.3.</p> <p>Detail view dimensions: (0.9), 0.3^{+0.10}/_{-0.05}, (0.4^{+0.10}/_{-0.05}), 0.05±0.05, 0.10, 0.95±0.15.</p>	<p>Pad layout dimensions: 1.3, 1.9, 0.3, 0.8, 0.6, 0.7.</p>