

Unit: mm

封装名	外形尺寸图	推荐焊盘尺寸图
<p style="text-align: center;">SOP-10A</p>	<p>Top view dimensions: 5.0±0.2, 10, 6, 4.4±0.2, 0.8MAX, 1.0, 5.</p> <p>Side view dimensions: 0.15^{+0.10}/_{-0.05}, 0.4±0.2, 6.2±0.3, 0~10°.</p> <p>Bottom view dimensions: (1.5), 0.10, 0.05±0.05, 0.12, 0.05±0.05, 1.55±0.15.</p>	<p>Pad dimensions: 5.90, 1.10, 0.45.</p>
<p style="text-align: center;">SOP-16B</p>	<p>Top view dimensions: 10.2±0.3, 16, 4.4±0.2, 0.955max., 1.27.</p> <p>Side view dimensions: 0.15^{+0.10}/_{-0.05}, 0.4±0.2, 6.2±0.3, 0~10°.</p> <p>Bottom view dimensions: (1.5), 0.10, 0.4±0.1, 0.12, 0.05±0.05, 1.55±0.15.</p>	<p>Pad dimensions: 5.80, 1.10, 1.27, 0.80.</p>