

封装

封装名	外形尺寸图	推荐焊盘尺寸图
<p>SOP-7B</p>	<p>Top view dimensions: 5.0±0.3, 1.67±0.20, 4.4±0.2, 0.895max., 1.27, 0.4±0.1, 0.12, 0.05±0.05, 1.55±0.15, 0.10, (1.5).</p> <p>Side view dimensions: 0.15^{+0.10}/_{-0.05}, 0.4±0.2, 6.2±0.3, 0~10°.</p> <p>Bottom view dimensions: 0.4±0.1, 0.12, 0.05±0.05, 1.55±0.15, 0.10, (1.5).</p>	<p>Pad dimensions: 2.07, 5.80, 1.10, 1.27, 0.80.</p>
<p>SOP-8D</p>	<p>Top view dimensions: 5.0±0.3, 4.4±0.2, 0.895max., 1.27, 0.4±0.1, 0.12, 0.05±0.05, 1.55±0.15, 0.10, (1.5).</p> <p>Side view dimensions: 0.15^{+0.10}/_{-0.05}, 0.4±0.2, 6.2±0.3, 0~10°.</p> <p>Bottom view dimensions: 0.4±0.1, 0.12, 0.05±0.05, 1.55±0.15, 0.10, (1.5).</p>	<p>Pad dimensions: 1.27, 5.80, 1.10, 0.80.</p>