

封装

封装名	外形尺寸图	推荐焊盘尺寸图
<p><b>SC-82ABB</b></p>	<p>Top view dimensions: 2.0±0.1, 1.3±0.2, 0.3, 0.3, 1.25±0.10, 0.3, 0.3, 0.3, 0.4, (0.15)</p> <p>Side view dimensions: 0.125<sup>+0.100</sup>/<sub>-0.025</sub>, (0.3), 2.1±0.1</p> <p>Detail view dimensions: 0.3<sup>+0.10</sup>/<sub>-0.05</sub>, (0.4<sup>+0.10</sup>/<sub>-0.05</sub>), 0.10, 0.05±0.05, 0.9±0.1</p>	<p>Pad layout dimensions: 1.3, 1.9, 0.3, 0.8, 0.6, 0.7</p>
<p><b>SC-88A</b></p>	<p>Top view dimensions: 2.0±0.1, 0.65, 0.65, 1.25±0.1, 6, 4, 1, 3</p> <p>Side view dimensions: 0.125<sup>+0.100</sup>/<sub>-0.025</sub>, (0.3), 2.1±0.1</p> <p>Detail view dimensions: 0.22<sup>+0.10</sup>/<sub>-0.05</sub>, (0.85), 0.10, 0.10, 0.05±0.05, 0.9±0.1</p>	<p>Pad layout dimensions: 0.65, 0.65, 1.8, 0.7, 0.35</p>