

Unit: mm

封装名	外形尺寸图	推荐焊盘尺寸图
TO-252-5A	<p>Top view dimensions: 6.60±0.20, 5.34±0.20, 6.10±0.20, 2.70±0.20, 9.90±0.30, 1.10±0.20, 1.27, 0.50±0.10, 0.127, 0.50±0.10, 1.524^{+0.254}/_{-0.127}.</p> <p>Side view dimensions: 0.50±0.10, 1.524^{+0.254}/_{-0.127}.</p> <p>Bottom view dimensions: 0.127max, (1.00), 2.30±0.20, (5.04), (3.56), (4.06), (5.51), (1.50), (4.19).</p>	<p>Pad dimensions: 5.34, 5.61, 6.33, 1.92, 0.65, 1.27.</p>
TSOP-8A	<p>Top view dimensions: 2.0±0.1, 2.3±0.1, 0.35MAX, 0.5, 0.13^{+0.10}/_{-0.05}, MIN0.1, 3.1±0.1, 0~10°.</p> <p>Side view dimensions: 0.13^{+0.10}/_{-0.05}, MIN0.1, 3.1±0.1, 0~10°.</p> <p>Bottom view dimensions: 0.2±0.05, 0.10, 0.05±0.05, 0.75±0.15, 0.10, 0.10.</p>	<p>Pad dimensions: 0.95, 0.95, 2.4, 1.0, 0.7.</p>