

封装

封装名	外形尺寸图	推荐焊盘尺寸图
SOP-16B	Top view dimensions: 10.2±0.3, 16, 9, 4.4±0.2, 1.27, 0.955max. Side view dimensions: 0.15^{+0.10}/_{-0.05}, 0.4±0.2, 6.2±0.3, 0~10°. End view dimensions: (1.5), 0.05±0.05, 1.55±0.15, 0.4±0.1, 0.10, 0.12.	Pad dimensions: 1.27, 0.80, 5.80, 1.10.
SOP-28B	Top view dimensions: 17.6±0.3, 28, 15, 7.6±0.2, 1.27, 0.845max. Side view dimensions: 0.2^{+0.10}/_{-0.05}, 0.5±0.2, 9.9±0.3, 0~10°. End view dimensions: (1.8), 0.05±0.05, 1.85±0.15, 0.4±0.1, 0.10, 0.12.	Pad dimensions: 1.27, 9.40, 0.60, 1.20.